[New 300-101 PDFValid Braindump2go 300-101 VCE and PDF Dumps 332q Offer[141-150

2017 New Cisco 300-101 Exam Dumps with PDF and VCE 332Q&As Free Updated in www.Braindump2go.com Today!100% Real Exam Questions! 100% Exam Pass Guaranteed!1.|2017 New Version 300-101 Exam Dumps (PDF & VCE) 332Q&As Download:http://www.braindump2go.com/300-101.html 2.|2017 New Version 300-101 Exam Questions & Answers Download: https://drive.google.com/drive/folders/0B75b5xYLjSSNQTNkemNFVU5QeDg?usp=sharing   QUESTION 141What is the primary service that is provided when you implement Cisco Easy Virtual Network? A.   It requires and enhances the use of VRF-Lite.B.   It reduces the need for common services separation.C.   It allows for traffic separation and improved network efficiency.D.   It introduces multi-VRF and label-prone network segmentation. Answer: C QUESTION 142Refer to the following configuration command.router (config-line)# ntp master 10Which statement about this command is true? A.   The router acts as an authoritative NTP clock and allows only 10 NTP client connections.B.   The router acts as an authoritative NTP clock at stratum 10.C.   The router acts as an authoritative NTP clock with a priority number of 10.D.   The router acts as an authoritative NTP clock for 10 minutes only. Answer: B QUESTION 143Which Cisco VPN technology can use multipoint tunnel, resulting in a single GRE tunnel interface on the hub, to support multiple connections from multiple spoke devices? A.   DMVPNB.   GETVPNC.   Cisco Easy VPND.   FlexVPN Answer: A QUESTION 144A router receives a routing advertisement for the same prefix and subnet from four different routing protocols. Which advertisement is installed in the routing table? A.   RIPB.   OSPFC.   iBGPD.   EIGRP Answer: D QUESTION 145Refer to the exhibit. Which statement is true? A.   Traffic from the 172.16.0.0/16 network will be blocked by the ACL.B.   The 10.0.0.0/8 network will not be advertised by Router B because the network statement for the 10.0.0.0/8 network is missing from RouterB.C.   The 10.0.0.0/8 network will not be in the routing table on RouterB.D.   Users on the 10.0.0.0/8 network can successfully ping users on the 192.168.5.0/24 network, but users on the 192.168.5.0/24 cannot successfully ping users on the 10.0.0.0/8 network.E.   Router B will not advertise the 10.0.0.0/8 network because it is blocked by the ACL. Answer: E QUESTION 146Which technology was originally developed for routers to handle fragmentation in the path between end points? A. PMTUDB. MSSC. windowingD. TCPE. global synchronization Answer: A QUESTION 147A network engineer is investigating the cause of a service disruption on a network segment and executes the debug condition interface fastethernet f0/0 command. In which situation is the debugging output generated? A.   when packets on the interface are received and the interface is operationalB.   when packets on the interface are received and logging buffered is enabledC.   when packets on the interface are received and forwarded to a configured syslog serverD.   when packets on the interface are received and the interface is shut down Answer: A QUESTION 148Which two commands would be used to troubleshoot high memory usage for a process? (Choose two.) A.   router#show memory allocating-process tableB.   router#show memory summaryC.   router#show memory deadD. router#show memory eventsE.   router#show memory processor statistics Answer: AB QUESTION 149Refer to the exhibit. The DHCP client is unable to receive a DHCP address from the DHCP server. Consider the following output:hostname RouterB! interface fastethernet 0/0ip address 172.31.1.1 255.255.255.0interface serial 0/0ip address 10.1.1.1 255.255.255.252!ip route 172.16.1.0 255.255.255.0 10.1.1.2Which configuration is required on the Router B fastethernet 0/0 port in order to allow the DHCP client to successfully receive an IP address from the DHCP server? A.   RouterB(config-if)# ip helper-address 172.16.1.2B. RouterB(config-if)# ip helper-address 172.16.1.1C.   RouterB(config-if)# ip helper-address 172.31.1.1D.   RouterB(config-if)# ip helper-address 255.255.255.255 Answer: A QUESTION 150If the total bandwidth is 64 kbps and the RTT is 3 seconds, what is the bandwidth delay product? A.   8,000 bytesB.   16,000 bytesC.   24,000 bytesD.   32,000 bytesE.   62,000 bytes Answer: C !!!RECOMMEND!!! 1.|2017 New Version 300-101 Exam Dumps (PDF & VCE) 332Q&As Download: http://www.braindump2go.com/300-101.html 2.|2017 New Version 300-101 Study Guide Video: YouTube Video: YouTube.com/watch?v=7DNc6Sp9S6E